

Is the screw shaft fitted with a continuous liner the whole length of the stern tube  Is the after end  
in the propeller boss  If the liner is in more than one length are the joints burned  If the liner do

Copy.

Copy of telegram from The Rt.Hon.Lord Pirrie.  
K.P.P.C.

WE APPROVE GENERALLY OF PROPOSED REPAIR BUT WOULD LIKE  
TO SEE THE PLATE FITTED UNDER THE FLANGE OF THE BEARING ALSO  
PREFER FITTED BOLTS TO SET PINS. WE ARE SENDING SKETCH OF  
SIMILAR REPAIR WE HAVE CARRIED OUT.

(Sgd) Pirrie.

N.B. The sketches in question have not yet come to hand.  
Immediately we receive them we will forward them on to you.



© 2020

Lloyd's Register  
Foundation

Thickness 1" Material of Lower back plate Steel Thickness 1" Greatest pitch of stays 14 1/2" Working  
Thickness 3/4" Material of tube plates 1/2" Thickness Front 1" Back 3/4"