

Surveyors *20/6/11*

Received from Chief Surveyors

NAME *Stl. S.S. "Helvetia"*

Report *Nwc.* No. *60354.*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Survey *1st Entry.* When due

It is submitted the Builders be informed that in view of this vessel not being fitted with cargo battens the class assigned is in accordance with paragraph 6, Section 42, of the Rules, and that to entitle the vessel to have this condition removed from her classification cargo battens should be fitted as required by paragraph 5, Section 42, of the Rules.

The Certificate should be returned to the Builders.

M. R.H.
20/6/11
Cole



© 2020

Lloyd's Register
Foundation

W 878-0116