


Messrs. Wm. Hamilton & Co.'s S.S. No. 232.


It would appear from the Surveyor's letter in regard to this case that an anchor attachment consisting of three long links has been supplied as for a $2\frac{1}{4}$ " cable, whereas the cable to which this attachment is to be fitted is $2\frac{5}{16}$ ". The Manufacturers, who admit that a mistake has been made, explain that the actual size of the attachment as supplied is $3\frac{14}{32}$ " whereas that which should have been supplied would have been $3\frac{15}{32}$ " in diameter.

In all the circumstances of the case, it is considered that the attachment supplied in this case may be approved and that the Greenock Surveyors should be informed accordingly.


16.3.12
sd 21.3.
ends.




20.3.12.



FRI. MAR. 22. 1912

approved. 



© 2020

Lloyd's Register
Foundation