

2m,7,16.

29 NOV 1916

Received by Chief Ship Surveyor 28.11.16

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. John Miles Rpt. Sld No. 26856

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey Damage

It is submitted the Sunderland Surveyors be requested to state whether nos 2 3 4 & 5 shell plates in E strake & the indented framing & bulkhead wing plate in way have now been repaired as recommended by the Newcastle Surveyors in June last.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

A.P.  
29.11.16

Classing th. to Sld: 11716

© 2021

Lloyd's Register  
Foundation

W883-0122