

17 FEB 1917

ent to Chief Surveyors

Received from Chief Surveyors

ESSEL'S NAME

16217
Sd. ss. Greston

Report

Hul

No. 54672

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

No. Boiler SURVEY PARTLY HELD.

When due

576

When proposed to be completed

Portion of Survey held, &c.,

To complete the boiler survey due 5. 16 & partly held at Hull in 11. 16 the donkey boiler safety valves require to be adjusted.

It was stated that this would be done in London now but the Superintendent states that owing to the difficulty of obtaining tubes for the starboard boiler he is unable to do it.

He further states he has information from the tube manufacturers that will enable him to have the survey completed on the vessel's return.

It is submitted action in the meantime might be deferred.