

Dublin, 22<sup>nd</sup> Feb'y 1916

of "Fergu".

Dub. Rpt 3569.

It is submitted that this report be returned to the Dublin Surveyor & he should be requested to fill in his recommendation.

It should be pointed out to him that in his report he states that the capacity of the dynamo is 40 Amperes, whereas he states that the main cable carries 49.8 Amperes, if the cable carries 40 amperes its area requires by Rule to be .017 sq. ins. & if 49.8 Amperes .025 sq. ins. he should therefore state which is <sup>the</sup> correct Amperage.



© 2020

Lloyd's Register  
Foundation

W28810025