

5m.10.38.

73 JAN 1941

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME "TEDDY" Rpt. Cbo No. 1106A

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The COLOMBO Surveyor reports failure of  
a repaired length of chain cable during test.

The Surveyor recommends the length of chain  
cable be repaired at the earliest opportunity.

It is submitted the vessel appears worthy  
to remain as classed without record of survey, subject as  
recommended.

As Now, Subject, etc.

Note The vessel is reported a casualty.

*[Signature]*  
1.1.40



© 2021

Lloyd's Register  
Foundation  
W 89-0115