

NEW YORK

July 6, 1914.

ALBERT W. MURRAY

the Owners' Representative, survey the steel screw steamer "INDIAN PRINCE" of Newcastle, 2846 tons gross register, for the purpose of ascertaining the nature and extent of damage stated to have been sustained by possibly striking a submerged object on 14th April 1914, while on a voyage from New York to Pernambuco.

For further particulars see log books.

Upon examination on 18th June 1914, the vessel lying on dry dock at Brooklyn, N.Y. the propeller shaft having been drawn in for examination as recommended Found:-

Two blades of the solid four bladed cast iron propeller broken at the tips and the boss showing signs of a fracture in the key way.


RECOMMENDED.

A new propeller of similar design and material to be supplied.

Upon completion of repairs the propeller shaft to be replaced and the new propeller fitted and secured.

FEE \$45.00

(sgd) A. W. Murray.



© 2020

Lloyd's Register  
Foundation