

grams—"TRANSPORTS, VIC, LONDON."

Any further communication on this subject should be addressed to—

The Director of Transports and Shipping,
Ministry of Shipping,
St. James's Park,
London, S.W.,

and the following number quoted,

T.A. 9935/1917, *du.*

LLOYD'S REGISTER OF SHIPPING
23 APR 1917
MINISTRY OF SHIPPING,
TRANSPORT DEPARTMENT,

April, 1917.

Sir,

With reference to your report of Survey of damage to the tank top plating in Nos. 2 and 3 Holds of the Transport s.s. "HARMATTAN" in the Roath Dock, Cardiff, on the 24th ultimo, and subsequent dates, a copy of which report has been forwarded by the Owners at the request of the Ministry, I have to ask whether you are able to give a definite opinion as to whether the corrosive action on the plating was caused by urine.

I am,
Sir,
Your obedient Servant,

G. C. Duggan
Director of Military Sea Transport.

Local Surveyor,
Lloyd's Register of Shipping,
Merchant's Exchange,
Bute Docks,
Cardiff.



© 2020

Lloyd's Register
Foundation

Bo


B/ 1973 17 25

17/08/71

Also for

LONDON

PLATES 1002 017



© 2020

Lloyd's Register Foundation

Chief Ship Surveyor

NAME She

emarks of the O

("The endorsement to bring out close presented in the

Survey Red

She cle

side (re

best dry

Owners'

the 1000

She Car

holds 1

in h. 2

reaching

temper

nothing

of shell

at the

within

shall

by the