


sp. "Sigulina".

New. Rpt. No. 64996.

It is submitted, the Newcastle Surveyors should be requested to state whether the surface of the front tube plates is included in the total heating surface given in their report as from the boiler plan this appears to be the case & which is not in accordance with the Rules.



Lloyd's Register
Foundation

JWR
24/10/13

GR
2020

18910150