

d by Chief Ship Surveyor 29.10.15

Received from Chief Ship Surveyor

EL'S NAME S.S. "Enosis" 77

Rpt. Hms. No. 3323.

e remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

e of Survey

## DAMAGE.

Damage through fire in Bunkers

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	-	-					
Removed and faired or repaired.....	3	1 web					
Faired or repaired in place.....	-	-					

Other items:- Vessel examined in Dry Dock. Bottom cleaned and coated. Bunker Casings repaired and minor repairs effected.

It is submitted the vessel is worthy to remain as classed with  
record of Survey 10.15 as recommended

100 A.1.

10.15 Qms.

Wms.  
30.10.15



© 2020

Lloyd's Register  
Foundation