

COPY.

1st July, 1908.

Sir,

Reverting to your letter of the 15th ultimo enclosing one from Mr. Hollison respecting the machinery of the Steam Drifter "ENZIE" I have to acquaint you that the Aberdeen Surveyors have confirmed the statement in Mr. Hollison's letter that the shafting was not correctly aligned, and it is suggested that the Engineer Surveyors should urge upon the makers of these small engines the importance of accuracy of adjustment of the various parts of the machinery.

I have to add that it is understood that the new weigh shaft was fitted and the main shafting coupled up with the new bolts before the vessel sailed last Monday, everything at that time being satisfactory.

I am, Sir,

Your obedient servant,

Secretary.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register
Foundation

W892-0180