

WRECK BOX

No. 16787

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME STEEL S.S. "FLORENCE JOHNSON" Rpt. H. L.

No. 31190

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 3712

Depth "d" 1216

Framing Table No. 3

Description Single angle as approved

Longitudinal No. 5134

Proportions Length = 1024
Depth =

~~Deck~~ Sheer stake .62" instead of .38" as required.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A.1. (Steel) Steam Trawler as recommended.

1 Dk. (steel).

BK 7½ 4BH Cem. Lloyd's A.&C.P. Q.78' F 19'.

Date of Build 5-9

[Signature]

7.7.19

The Surveyor should be requested to forward the usual report on forgings.



© 2020

Lloyd's Register
Foundation

W893-0029 1/2

W893-0029 2/2