

Number of Masts ...	Two	aft side of the head of the stern post ...	305
Rigged ...	Schooner	Length at quarter of depth from top of weather deck at	305

of "Fulgens." Sld. Rpt. No 25461.


It is submitted that before this case receives the consideration of the Committee, the Newcastle Surveyors should be requested to say whether they are correct in stating that one $3\frac{1}{2}$ " centre suction in each hold well has been fitted as it is not clear from their report whether the wing suctions in these holds have also been fitted in accordance with the approved plan & the Secretary's letter dated 7. 6. 17.

The pumping plan should be forwarded to them which they should return with their reply.

JRS

JWR.
17/11/17

Ln: -12/1/17



© 2020

Lloyd's Register
Foundation

W902-0009