

Propeller changed & shaft
etc on a

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to run the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

5.3.14.

S.A.
18.3.14

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation