

3m.9.9.

Wood 15.

WRECK BOX

No. 15 Bottom

Received by Chief Ship Surveyor 19. 12. 10.

Received from Chief Ship Surveyor

VESSEL'S NAME *C.S.S. "Flamingo"* Rpt. *Aut.* No. *23240*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Condition. 1st S.S. No. 1 due 10, 10.

Stranded 2/11

This vessel has been examined on a slipway, the bottom cleaned and coated.

The 1st.S.S.No.1 became due in October last, and it is proposed to hold it next Summer.

It is submitted this proposal might be approved, and action in the meantime deferred.



RBF
© 2020
19/10/10

Lloyd's Register
Foundation