

W.L.  
total

2m17.16.

WRECK BOX  
No. 3-8

13

1

Received by Chief Ship Surveyor

13-12 K

Received from Chief Ship Surveyor

4 DEC 1916

VESSEL'S NAME

Steel S.S. Dunraven

Rpt.

Cy

No. 39257

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/3/92.)

Nature of Survey

DAMAGE.

Damage through whilst coaling in Fleet

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Sk. Plates
Renewed .....							
Removed and faired or repaired.....	3	2					
Faired or repaired in place.....	1	1					

Other items:-

Vessel examined in drydock

Bottom coated

Minor repairs effected

It is submitted the vessel is worthy to remain as classed with  
record of Survey 12-16 as recommended

100-A-1

12-16

W914-0075



© 2020

Lloyd's Register  
Foundation