

Less Navig  
+ Inc.  
Register  
as out on

by Chief Ship Surveyor 14/2/10.  
Received from Chief Ship Surveyor \_\_\_\_\_  
VESSEL'S NAME Stl. S. S. "Boverton" Rpt. hwc. No. 57972  
Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey 1st Entry.

It is submitted that, before this case receives the consideration of the Committee, the Newcastle Surveyors should be requested by wire to state whether the stream chain, towline, hawsers and warps have been supplied to this vessel in accordance with Table 22 of the Rules; and answer this request by wire.

TEL. 15/2/10.

Mr R.A.  
15/2/10

Boverton  
Stl. S. S.  
hwc.  
14/2/10

FROM