

7.  
Inspected by Chief Ship Surveyor

5/8/08

Received from Chief Ship Surveyor

VESSEL'S NAME

Stl. S.S. "Buika"

Rpt.

Mdl

No. 5521.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Signature of Surveyor

First Entry.

It is submitted the Sunderland Surveyors be informed that this vessel has proceeded to Sunderland where her machinery is to be placed on board at the works of the North Eastern Marine Engineering Company, and that to complete the Hull the following requires to be done:— the tunnel in the after hold clear of the after recess to test, the downton pump to test, the steam steering gear and windlass test under steam and the beams and casing removed for shipping the machinery to be replaced and riveted up. They should be requested to give these matters the necessary attention and forward a report on form No.8 with a view to the classification of the vessel.

Ins. to Sld  
6/8/08.

C.F. R.C.  
6/8/08



© 2020

Lloyd's Register  
Foundation