

Hull Rpt No. 30. 150

Port of HULL,

22nd. August. 1917.

REPORT ON MASTS, SPARS, AND RIGGING.

Gentlemen,

Having, in accordance with your instructions, examined
the Masts, Spars, and Rigging, and Iron Work of same, of the

S.S., "CAMBRIC",

I have to report that I found the following on the FORE MAST.

All shrouds and topmast back stays found defective and
recommended to be renewed all goose neck bolts and pins
to be overhauled.

- MAIN MAST. -

All shrouds and topmast back stays found defective and
recommended to be renewed all goose neck bolts and pins
to be overhauled.

Mast widges to be taken out for examining masts.

With the above exceptions everything found in order.

Robt Martin

Fee £ - 10 - =

To the Surveyors,

Lloyd's Register of Shipping,

HULL.



© 2020

Lloyd's Register
Foundation

W 918 - 0105