

1,500,10,17.

sent to Chief Surveyors

19.11.14

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "Clifton"

Report hwc.

No. 40428


For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.32.)

Nature of Survey

When due

To complete the 1st S.S. no. 3, due 2.16. See Cardiff Rpt. no. 39384.
Some repairs are required in lower bunkers.
Damage repairs to be made permanent as per Off. rpt. no. 39384.
as marked in pencil.



© 2020

Lloyd's Register
Foundation

W919-0107

Wicks
20.11.14