

to Chief Surveyors 2-4-14

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel S.S. "Chorley"Report H.Yk.No. 13644.**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**


(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage

When due \_\_\_\_\_

Notes:

The Class of this vessel is subject to 3 deck plates being renewed and the Steering Engine repaired at the first favourable opportunity.



W920-0118

© 2020  
Lloyd's Register  
Foundation