

2m, 7, 16.

WRECK BOX
No. 44
GOVERNMENT SERVICE.

22 SEP 1916

1

Received by Chief Ship Surveyor 21.9.16

Received from Chief Ship Surveyor

VESSEL'S NAME

Hull's Broomhill

Rpt. Cff

No. 39078

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

Grounding

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel examined in dry dock, bottom cleaned
& coated & minor repairs carried out


It is submitted the vessel is worthy to remain as classed with
record of Survey 9.16 as recommended

100A-1

9.16 Cff

M
22.9.16

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation

11924-0022