

In damage cases where the Surveyor has not made a special survey
offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned)
painted on Ship and now ver

11,39.

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor

SSEL'S NAME "YIDO" Rpt. Ssk. No. 998

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A bower anchor requires to be supplied.

The Susak Surveyor rep

The Susak Surveyor reports this vessel afloat and

a bower anchor placed on board.

It is submitted the vessel appears worthy to remain
as classed without record of survey. *Without Condition*

Delete from S.R.L.

Wals
18.4.40



© 2020

Lloyd's Register
Foundation

W93-0081