

Less Crew Space
Less above Crown of
Engine Room ..
TONNAGE FOR FEES ..
Less Engine Room ..

stern post ..
2nd Number ..
Proportions—Breaths to Length ..

5509
5.85

Managers
(Where necessary to be entered in Reg.)
Residence

TELEPHONE No. 610.



Lloyd's Register of British & Foreign Shipping,

Ocean Chambers, Lowgate,

Hull, 19th June 1906

S.S. "Anaconda"

Reference

This report has been kept back in order to ascertain the Owners opinion in regard to the deficiency in the weight of the chain cable. This was first attempted through the Builders, but apparently they forgot all about it and did not communicate with the Owners, we therefore wrote to the Owners and their reply is forwarded herewith.

arew



© 2021

Lloyd's Register
Foundation

Spacing ..
PILLARS, In 'tween Decks, Size and Spacing
Hold ..
" 2½" As arranged.

Tie Plates
Deck, Material and thickness
Forecastle Deck Stringer Plate, brdth & thckns