

3m, 12, 16.

Wreck 6-17

Received by Chief Ship Surveyor

Feb 7. 17

2 FEB 1917

Received from Chief Ship Surveyor

VESSEL'S NAME

SS "Bilwood"

Rpt.

Kul

No.

29792

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/12.)

Nature of Survey

Condition

Damage

The class of this vessel is subject to the bulwarks being repaired at the first convenient opportunity.

The Hull Surveyors now report the vessel has been placed in dry dock. The bottom cleaned & coated.

The bulwarks have not been repaired at this time.

It is submitted the vessel appears worthy to remain as classed with fresh record of survey subject as above.

100 A.1

2.17 Kul.

Subj
etc

17
12



© 2020

Lloyd's Register Foundation

w934-0001

Surveyors are

Committee