

50,12,16.

1

Sent to Chief Surveyors 5.278.

Received from Chief Surveyors 6 FEB. 1918

VESSEL'S NAME *S.S. Carmen* Report *Cpn* No *423*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

Instructions are requested regarding equipment.

Under the modified rule the vessel only requires to be supplied at present with 210 fath. of chain cable instead of 240 fath. as previously required, & therefore only 75 fath. of cable requires to be supplied, of as stated, in Cpn report No 5396 there are 135 fath. of cable aboard.

*In Dr. J.A. Still
to note.*

6.2.18.



© 2020

552.18

Lloyd's Register
Foundation