

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.

20th October, 1915

Dear Sirs,

With reference to your report No. 4773 on the Machinery of the new steamer S.S. "CARMEN", I shall be glad if you will let me know whether you are correct in stating that the diameter of the H.P. cylinder is 14", as in the launching report you stated it to be 15".

You should also state whether the superheater safety valve is fitted with means of lifting and turning the valve, in order to test its efficiency under steam, in accordance with section 3 Paragraphs 6 & 8 of the Society's Rules. Also whether the same applies to the sister vessel "ANNA"; your report No. 4257.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

COPENHAGEN.



© 2020

Lloyd's Register
Foundation