

13 OCT 1917

Surveyors 12-10-17

Received from Chief Surveyors

NAME *St. S. "Cayo Bonito"* Report *Hull* No. *30046*For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

No. *Boiler* SURVEY PARTLY HELD.*8.16*

When proposed to be completed

Survey held, &amp;c.,

To complete the boiler survey due 8.16 and partly held in Hull in July last, the donkey boiler safety valves require to be adjusted.

The Owners state that the vessel is on Government Service and as soon as they can communicate with the Captain they will arrange for the survey to be completed.

It is submitted action might be deferred.

*AWD**13/10/17*

© 2021 Lloyd's Register Foundation

W937-0071