

2

5 FEB 1915

Sent to Chief Surveyor

Received from Chief Surveyors

VESSEL'S NAME

4. 275

Report

Hurl.

No. 27983

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases where repairs have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No. *Boiler* SURVEY PARTLY HELD.

When due


7. 14

When proposed to be completed

Portion of Survey h. &c

To complete the boiler survey due 7. 14 the safety valves remain to be adjusted. The Owners state that the vessel is much overdue & fears are entertained for her safety. It is submitted action be deferred.

JWZ
5/27/15
JFB



© 2020

w938-0072

Lloyd's Register
Foundation