

13 MAY 1919

Received from Chief Ship Surveyor

Ship Surveyor

Steel S.S. "CHARLES TELLIER".

Rpt.

P. Sd.

No. 1373

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to set out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


The class of this vessel is subject to some indented plating being dealt with, and to a lifeboat being ~~supplied~~ repaired.

The Port Said Surveyor now reports that the lifeboat has been repaired.

The vessel appears worthy to remain as classed without record survey, subject to indented plating etc. being repaired, but without special conditions as regards lifeboat.

As now, subject etc.

Without etc.



© 2020

13. 5. 19.
Lloyd's Register
Foundation

4939-0058