

Surveyors

12. 8. 03.

Received from Chief Surveyors

NAME

Wood Schooner "Countess of Ranfurly" Report

Auk No. 183<sup>C</sup>

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Key

Equipment.

When due

It is submitted that before this case reaches the consideration of the Committee, the Superintendents of the Society's Proving Houses at Cardiff & Chester should be informed that an anchor bearing the following marks, has been supplied to this vessel, and each should be requested to furnish full particulars of weight, test &c. also weight of stock, if the anchor has been tested at his machine.

(Weight) 7-0-3.

R. H.  
A.

 C. 5198.

The Society's Superintendent of the Society's Proving House at Tipton should be informed that ~~chain cables as follows have been supplied to this vessel, and they should be requested to furnish the weights of the various lengths marked as follows:~~

45 fms 1" stud link chain cable, tests 18 &amp; 27 tons. LPH-T 23843.

15. 0° 0° 0° 0° 21741.

14 <sup>3</sup>/<sub>4</sub>. 0° 0° 0° 0° 21740.14 <sup>1</sup>/<sub>2</sub>. 0° 0° 0° 0° 21745.

75. 0° 0° 0° 0° 25263.

Lrs: - 14/8/03

W941-0198

Lloyd's Register  
Foundation  
14/8/03