

S.S. "Crispin." Sir Raylton Dixon No. 2534.

As directed examined Spindle to Hand
Steering gear and am of opinion that a
support is needed and should be fitted as
recommended by the Middlesbrough Surveyors.

Met on board Captain Williams, the master,
and Mr. Watson, an assistant to Mr. Isaacs
the owners Superintendent, who stated that
as they were in a hurry for the vessel, it
was arranged with the Builders to fit the
support to the spindle, and a number of minor
items, on the vessels return to UK in March
next, and produced a list of said items
including the one in question.

SW 11-12-04



© 2020

Lloyd's Register
Foundation