

Received by Chief Ship Surveyor 22.1.17

Received from Chief Ship Surveyor _____

VESSEL'S NAME DR Ack Dauntless Rpt. Hul No. 24588

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE. + ConditionDamage through heavy weather.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

A number of shell rivets renewed & butts & plate edges overhauled.

Bottom examined on slipway.

It is submitted the vessel is worthy to remain as classed with record of Survey 1.17 Hul as recommended

100 AI Steamer Trawler
1.17 Hul

MEI.



© 2020

Lloyd's Register
Foundation

W46-0584