

F.E.

Received by Chief Ship Surveyor 29/8/06

Received from Chief Ship Surveyor

VESSEL'S NAME Sit S.S. "Dipton"Report AprNo. 13044

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>5' less but compensated for by increased thickness of strake above</u>	
Spar Sheerstrake . .	<u>2' 20</u>	<u>Proportions</u>
Description of Framing:— <u>Bulb angle increased to compensate (viz., ordinary, deep, zed, channel or bulb-angle). for wider spacing.</u>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A.1 (plus) Spar deck with freeboard," as recommended. The Summer freeboard of 5' 8 1/2 from centre of disc to top of statutory deck line at spar deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

+ 100 A.1 (plus) Spar deck with freeboard
Spar dk (pt du. pt str) 2 h B & web frames
W. B = Bulb DBa 112 n B + B 47 + 131 695t A B T 315
SK. 6 B 4, Cam. Lloyd's A 100 P 31 B 105 701