

WRECK BOX
No.

6-11

1 MAY 1917

1

Received by Chief Ship Surveyor 11.5.17

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. Boldwell Rpt. w hpl No. 15365

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/92.)

Nature of Survey DAMAGE.
The class of this vessel is subject to some tunnel cleading, deck stanchions etc. being repaired.

Damage through touching the ground & during coaling operations

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:- Vessel examined in dry dock
Bottom coated. minor repairs effected.


To Complete Damaged shell plating on starboard side
amidship to be repaired at first opportunity
Also

Damage mentioned above to be repaired

It is submitted the vessel is worthy to remain as classed with out
record of Survey as recommended

As now Subject

M
A.P.
12.5.17



© 2020

W949-0090

Lloyd's Register
Foundation
Foreig