

(Concl.) S. S. BOLDWELL

below them indented.

The Superintendent informed the undersigned that his damage was temporarily repaired at Glasgow between the 2nd + 5th Jan'y. 1914.

As the vessel was stated to be urgently required for the Admiralty Transport Service, nothing was done at this time to effect permanent repairs to the shell plating amidships on to the damage stated in Cardiff Report No. 38917.

D. M. Anglin.

PAR. B.—If this Report is copied by Conving Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

Iron Stream Chain)
or Steel Wire....)