

If the  
by the tanks

(2m, 9, 14 - 14)

2

Wreckg

WRECK BOX  
No. - Q. Bottom

Sent to Chief Surveyors 19.8.'15.

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl. S.S. "CLAN MACLEOD".

Report Gls. No. 35363

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

No. 3 SURVEY PARTLY HELD.

When due 9. 15. When proposed to be completed \_\_\_\_\_

Portion of Survey held, &c \_\_\_\_\_

Some repairs require to be effected to the No.3 Tank.  
To complete the Special Survey No.3- see Report.

*M*

20.8.'15



© 2020

Lloyd's Register  
Foundation

W 953 - 0088

3. - Transite  
to write on a  
Su  
St