

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 30/7/17 When handed in at Local Office 30/7/17 Port of Hull  
 No. in Reg. Book. 377 Survey held at Hull Date, First Survey 1917 Last Survey 1917  
on the Wood, Iron or Steel SC. SE BEECHPARK (No. of Vols) 1 Master  
 TONNAGE: 4763 Built at Greenock By whom Greenock & Glasgow When 1917 3  
 GROSS 3190 Owners L & J Denholm Port belonging to Greenock  
 UNDER DEK 3503 Owners' Address  
 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? dry Name of Dock Alexandra Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }  
 total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 17123 Port Gnk

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned and Expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>1-100/A. 3.17</u>		<u>1-LMC 3.17</u>
Society's Freeboard (if assigned) as painted on Ship and now verified } <u>—</u> ft. <u>—</u> ins.		

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? —

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Docking  
Vessel placed in dry dock, bottom + rudder cleaned  
examined + repainted.

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

## PRESENT CONDITION OF THE

Decks <u>good</u>	Stringers <u>seen good</u>	Dblg. Plates under Sounding Pipes <u>—</u>	Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month <u>—</u> Year <u>—</u>
Caulking of Decks <u>—</u>	Inner Bottom Plating <u>—</u>	Engine Room Skylights <u>good</u>	Boats <u>good</u>
Waterways <u>—</u>	State if Tanks have been examined inside <u>—</u>	<u>Condition</u> , Open'gs, Lids, &c. <u>—</u>	Masts, Yards, &c. <u>—</u>
Coamings <u>—</u>	State if Tanks now tested <u>—</u>	Scuppers <u>—</u>	Condition, how ascertained <u>from dx</u>
Beams & Fastenings <u>seen good</u>	Bulkheads <u>seen good</u>	Cargo Hatchways <u>—</u>	(State if wedges removed) <u>no</u>
Outside Plating <u>good</u>	Ceiling <u>—</u>	Hatches <u>—</u>	Sails <u>—</u>
Caulking of ditto <u>—</u>	Cement or Asphalt (State which.) <u>—</u>	Planking of Wood Vessels <u>—</u>	Equipment letter <u>W</u>
Rivets <u>—</u>	Rudder <u>good</u>	Caulking ditto <u>—</u>	Anchors, No. of <u>3B. 15. 1K.</u>
Breasthooks & Crutches <u>—</u>	Steering gear and its connections <u>—</u>	Treenails ditto <u>—</u>	Cables (State if now ranged) <u>no</u>
Transoms <u>—</u>	Windlass <u>—</u>	Breasthooks & Stemson ditto <u>—</u>	" length <u>staked</u>
Frames <u>BA. Port seen good</u>	Have Pumps now been examined and found efficient? <u>—</u>	Transoms, Pointers, & Crutches ditto <u>—</u>	" (on board) <u>complete</u>
Reverse Frames <u>—</u>	Have Sluice Valves now been examined and found efficient? <u>—</u>	Timbers of Frame at openings ditto <u>—</u>	" Rule length <u>—</u>
Floors <u>—</u>	Have Watertight Doors now been examined and found efficient? <u>—</u>	Ditto ditto at other places ditto <u>—</u>	Hawser & Warps <u>good</u>
Keelsons <u>—</u>		Stringers, Clamps & Shells ditto <u>—</u>	Standing & Running Rigging <u>—</u>
		Salting (State if examined.) ditto <u>—</u>	

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,1,1," or "to remain as classed and to have record of survey, 1,1,1, and the notations of ss No. 1-11 and pnd11, &c."

This vessel as far as seen is in good + efficient  
condition + eligible in my opinion to remain as  
classed + to have fresh record of survey 7-17

Survey Fee (per Section 22) ... £

Special Damage or Repair Fee (if any) (per Sec. 22) ... £

Travelling Expenses (if chargeable) ... £

Second Surveyor's Fee (if any) ... £

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character Assigned

FRI. 3 AUG. 1917

Lloyd's Register  
Foundation

W 954 - 0138