

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 15. 4. 1910 When handed in at Local Office 15. 4. 1910 Port of Middlesbrough

No. in Reg. Book

Survey held at Middlesbrough

Date, First Survey

Last Survey

YEAR. MONTH.

Built on the Wood, Iron or Steel S. S. Bengrave

Master

TONNAGE:-

GROSS 3850

UNDER DEK 3673

NET 2400

Built at

Sprockton

By whom

Craig Taylor & Co Ltd

When 1910

Owners

Joseph Hould & Co Ltd

Port belonging to

Liverpool

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock?

Yes

Name of Dock

Smiths

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet; }

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No.

Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 M Contemplated		

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. and.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Yes also whether any damage report was made, and, if so, by whom? Underwriters Rep.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Damage: stated due to striking bank

in River Tees

now done: Vessel placed in dry dock, bottom 4' d. on 1st side, forward end of bilge keel found slightly bent, now found in place, bottom otherwise in good condition

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	Stringers	Dbing. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels. (State if on Felt.) When put on, Month Year
Caulking of Decks	Inner Bottom Plating	Engine Room Skylights	Boats
Waterways	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Coamings	State if Tanks now tested	Scuppers	Condition, how ascertained (State if wedges removed)
Beams & Fastenings	Bulkheads	Cargo Hatchways	Sails
Outside Plating	Ceiling	Hatches	Equipment letter
Caulking of ditto	Cement or Asphalt (State which.)	Planing of Wood Vessels	Anchors, No. of
Rivets	Rudder	Caulking ditto	Cables (State if now ranged)
Breasthooks & Crutches	Windlass	Treenails ditto	" length (on board) size
Transoms	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	" Rule length (per Table 22) size
Frames	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawsers & Warps
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	Standing & Running Rigging
Floors		Ditto ditto at other places ditto	
Keelsons		Stringers, Clamps & Shells ditto	
		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,05," or "to remain as classed and to have record of survey, 1,05, and the notations of ss No. 1-05 and ptND05, &c."

This vessel is now in good condition, eligible in my opinion for the class contemplated.

Survey Fee (per Section 24) £

Special Damage or Repair Fee (if any) (per Sec. 24.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUES. 26 APR 1910

Character Assigned

See minute on J. Entry rpt
Mdb. No 6209



© 2020

Lloyd's Register Foundation

W955-082