

21 SEP 1917 <sup>1</sup>

ved by Chief Ship Surveyor 19.9.17

Received from Chief Ship Surveyor

SEL'S NAME Steel S. S. Dalgarnel Force Rpt. Hul No. 30740

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

DAMAGE.

Damage through collision

(see Dnr Rpt 1915)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Removed and faired or repaired.....							
Faired or repaired in place.....							1

Other items:- Vessel examined in dry dock Bottom coated  
Bulwarks repaired Minor repairs effected

Wear & Tear

Forecastle and bridge decks caulked & painted

Some bottom plating is slightly set up & it is recommended it  
be faired at the Owners convenience.

It is submitted the vessel is worthy to remain as classed with

record of Survey 9.17 as recommended without etc & subject etc

100 A.1. } without etc  
9.17 Hull } Subject etc



© 2020

Lloyd's Register  
Foundation