

Wreck Box 5

WRECK BOX

No. 5 (Top)

24 SEP 1917

1

Received by Chief Ship Surveyor 22.9.17

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. Baykerran Rpt. Cff No. 39991

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/82.)

Nature of Survey

DAMAGE.

Damage through striking quay, fire etc

(see Cff Rpt 39486)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	6	1 ft					
Removed and faired or repaired.....	8	1 "		1			
Faired or repaired in place.....	4	4					

Other items:-

Vessel examined in dry dock Bottom coated  
Minor repairs effected

It is submitted the vessel is worthy to remain as classed with

record of Survey 9.17 as recommended without special condition.

100 A.1. Sp. Dk } without  
9.17 Cff

*M*  
*A.P.*  
22.9.17



© 2020

Lloyd's Register  
Foundation