

Chief Ship Surveyor 11.3.15.

Received from Chief Ship Surveyor

NAME Stl.S.S. "BEGA".

Rpt. Nwo.

No. 67255

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

### CONDITION.

This vessel has been placed in dry dock, bottom cleaned and coated.

2 shell plates were found to be indented but as the vessel is on Admiralty charter no repairs could be effected. The vessel's efficiency is not affected.


It is submitted the vessel appears worthy to remain as classed with fresh record of survey, subject to the indented plates being faired at the Owners' convenience as recommended.

100 A.1  
"Stm Hawker"

3.15 Shl.

{Subj-  
etc}

M.M. 15'  
11.3.



© 2020

Lloyd's Register  
Foundation

W961-0028