

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 9-3-15 19 When handed in at Local Office 9-3-15 19 Port of NEWCASTLE-ON-TYNE.

No. in Survey held at North Shields Date, First Survey 8 Last Survey May 8 1915
Reg. Book.

403 on the Wood, Iron or Steel Deck "Bega" Master

TONNAGE:-
GROSS 318
UNDER DECK 274
NET 131Built at Aberdeen By whom J. Guthrie & Sons Ltd When 1914-1
Owners New York Clean Tanky Co (Fleetwood) Port belonging to Fleetwood
Owners' Address
(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? In Name of Dock Band Destined Voyage

WB=Cell DBorDBa feet; uE&B feet; f feet; f feet; f
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 11386 Port Aberdeen

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. If for Special Survey, Date of last Survey and of Periodical Surveys.	MASS AND NO. OF EXPLD.	Machinery and Boiler Surveys (including date of N.B., if any).
4100 A1 Steam Trawler 1-14		42 Mac 1-14

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

Now done: Vessel placed in dry dock bottom & side cleaned & examined & washed
Found on the starboard side. The Clin plate 1st shake below sheer indicated on the Port side. No 2 plate in sheer shake indicated

As the vessel is an Admiralty Charter no repairs are effected

STATE OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Repaired or Repaired in place								
CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder
of Decks	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblg. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.
	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Caulking	Treenails	Breasthooks & Stems	Transoms, Pointers, & Crutches ditto
Fastenings	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shelves	Salting (State if examined.)	Copper, or I.M. of Wood Vessels (State if on felt.)	When put on, Month	Boats	Masts, Yards, &c.
ating	Condition, how ascertained	(State if redges removed)	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	" length (on board)	" Rule length
f ditto							Hawser & Warps.	Standing & Running Rigging
s & Crutches								
ames								

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptND11, &c."

This vessel is in my opinion in a good & efficient condition & capable to remain as classed with fresh record of survey 3-15 subject to the indicated plates being faired at the Owners convenience. The vessel appearing being not impaired

Survey Fee (per Section 28)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 28)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

TUE. MAR. 16. 1915

Surveyor to Lloyd's Register of British & Foreign Shipping

TUE. - MAY 1917

TUE. NOV. 13 1917.

© 2020

Lloyd's Register Foundation

W961-0029