

Received by Chief Ship Surveyor 30.6.02

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sck Ballesteros N° 3. Report Bbs No. 1376

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

DAMAGE.

Damage through grounding.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plate
Renewed .....	7	3	2				
Removed and faired or repaired .....	6		1	3			
Faired or repaired in place .....	6						

Other items:- Stem faired. Bilge Keel faired. Ceiling + Cement made good. a minor repairs.

It is submitted the vessel is worthy to remain classed 100 A1

with record of Survey 6.02 Bbs as recommended.

100 A1  
6.02 Bbs



© 2021

Lloyd's Register  
Foundation

to lower deck water line: the flat