

BARUNGA

Special Survey No.1 due June 1917 partly held by
the examination of the bottom and rudder in dry dock
and the examination of the anchors and cables,
decks, masts, rigging and steering gear.
Permanent repairs require to be effected to damaged
shell plating, frames, stringers etc.

The survey of the engines and boilers has been
completed.

W 963-2013

Lloyd's Register
Foundation