

Less above Crown of
 Engine Room ... 18.39
 TONNAGE FOR FEES... 4315.31
 Tonnage Engine Room 1434.87

2nd Number 30937.96
 Proportions—Breadth to Length 12.93

Managers ... (Where necessary to be entered in Reg. Book.)
 Residence Leadenthall

Chief Ship Surveyor 29/8/06

Received from Chief Ship Surveyor _____

NAME S.S. "Arino" Rpt. Aut No. 7120

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey First entry

It is submitted that this report be forwarded to the Glasgow Surveyors for their information.

S.B.
R.B.H.
C.H.J.
29/8/06

w969-0032



© 2020

Lloyd's Register
 Foundation

WEB-FRAMES, in Fore Body, No. and spacing
 " " " breadth, & thickness
 " No. of Side Stringers " "
 " " " " " "
 WEB-FRAMES, in E. & B. Space, No. & spacing

" Tie Plates ...
 " Deck. Material and thickness

Number.

STIFFENERS.