

COPY.

18th August, 1906.

Sir,

It is observed that the new steamer "ARRINO", recently built under special survey at your port, is reported to have grounded in the Clyde on the 10th instant, and to have been re-floated the same day.

As it is understood that the steamer was to be placed in dry dock for examination after the grounding, I shall be glad to learn whether this was done, and if so, whether an opportunity was afforded the Surveyors to make a careful examination of her and with what result.

I am, Sir,

Your obedient Servant,

Secretary to the
Classification Committee.

T. J. Dodd Esq.,

GLASGOW.

© 2020

Lloyd's Register
Foundation

W969-0035

Hold

~~Quarter 'tween Dks.~~

in Hold

0.1

II f.

1

1

Deck. Material and thickness

If Forecastle Deck Stringer Plate, b'dth & th'kns

* Angle on ditto