

*Jo Racio*

*Diesel 37*

F.E.

Received by Chief Ship Surveyor *12.6.07*

Received from Chief Ship Surveyor

VESSEL'S NAME *St. S. "San"*

Rpt. No. *53068*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .		
Spar Sheerstrake . .		
Description of Framing:— <i>Deep framing. 1/2" less in thickness, but (viz., ordinary, deep, zed, channel or bulb-angle). compensated by increased depth of girder.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100A1 ("Steel") as recommended.

$\pm$  100A1 ("Steel")

*1 DR (per plan & per spec) 2 to B & deep framing, 3 DR Rule.*

*W. B = Cell OB a 115' x E 21' f 150' 1036 t APT 136 t*

*FK 6 BH Cam. Lloyd's A9CP P41 B 179' F32*

*J.P.P.*



© 2019 Lloyd's Register Foundation

W97-0089