

REPORT OF SURVEY for REPAIR

LLOYD'S REGISTER OF SHIPPING

PORT GIBRALTAR

24th. August 1918

THIS IS TO CERTIFY that I have surveyed the Hull of the British Steamship "ARUM" Captain J. Williams said to have been caused in collision with s.s. "ROSSANO" on the 23rd. inst in Admiralty Harbour Gibraltar. and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have recommended that she be continued as now classed provided permanent repairs are carried out in a reasonable time : temporary repairs having been carried out by the Dockyard. Being fit to carry dry and perishable cargo in her present damaged condition.

(Sgd) S. Rider

Surveyor to Lloyd's Register

W 970-0038

Copper, or
(State
When
Boats.....
Masts, Y
Condition
(State
Sails.....
Equipmen
Anchors,
Cables (S
" leng
" Ru
Hawser &
Standing

vessel in the
to remain as

Lloyd's Register
Ink
on or below the line

out within a reasonable time.



© 2020

Lloyd's Register
Foundation